

EAST - [lined duct:2]

File View Edit Tools Window Help

Pending

Active

L1: (5) (("6,233,875") or ("6,447,047") or ("6,474,

L2: (11) ("3,989,275") or ("4,848,829") or ("5,298

L3: (214) (296/146.7).CCLS.

L4: (326) (296/146.6).CCLS.

L6: (188381) 15 and foam or styrene or urethane

L7: (157) 15 and (foam or styrene or urethane)

L5: (384) (280/751).CCLS.

L8: (4) 17 and velcro

L10: (1) 19 and hook with loop

L11: (0) 19 and velcro

L12: (1092) 16 and velcro

L13: (1) 14 and velcro

L14: (1) 14 and hook with loop

L9: (167) (296/187.05).CCLS.

L15: (23) 13 and leather

L16: (1) ("3502056").PN.

L17: (1) ("5998015").PN.

L18: (1) ("4783114").PN.

Failed

(9260) 138/\$.ccls. and line\$

Saved

(5) (("5545361") or ("5799991") or ("5988713") or (

(17) ("5000510") or ("5121106") or ("5120007")

Search

List

Browse

Queue

Clear

DBs USPAT

☒ Highlight all hit terms initially

4783114

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (42)

UDC

Queue

Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error
7	IS&R	L5	384	(280/751).CCLS.	USPA T: U	2004/10/2 8 08:43		
8	BRS	L8	4	17 and velcro	USPA T	2004/10/2 8 08:28		
9	BRS	L10	1	19 and hook with loop	USPA T	2004/10/2 8 08:44		
10	BRS	L11	0	19 and velcro	USPA T	2004/10/2 8 08:44		
11	BRS	L12	1092	16 and velcro	USPA T	2004/10/2 8 08:44		
12	BRS	L13	1	14 and velcro	USPA T	2004/10/2 8 08:46		
13	BRS	L14	1	14 and hook with loop	USPA T	2004/10/2 8 08:46		
14	IS&R	L9	167	(296/187.05).CCLS.	USPA T: U	2004/10/2 8 09:03		
15	BRS	L15	23	13 and leather	USPA T	2004/10/2 8 08:53		
16	IS&R	L16	1	("3502056").PN.	DERW ENT	2004/10/2 8 09:15		
17	IS&R	L17	1	("5998015").PN.	USPA T	2004/10/2 8 09:40		
18	IS&R	L18	1	("4783114").PN.	USPA T	2004/10/2 8 09:40		

Hits

Details

HTML

Ready

NUM

BEST AVAILABLE COPY

EAST - [lined duct:2]

File View Edit Tools Window Help

Pending

Active

L1: (5) ("6,233,875") or ("6,447,047") or ("6,474,

L2: (11) ("3,989,275") or ("4,848,829") or ("5,298

L3: (214) (296/146.7).CCLS.

L4: (326) (296/146.6).CCLS.

L6: (188381) 15 and foam or styrene or urethane

L7: (157) 15 and (foam or styrene or urethane)

L5: (384) (280/751).CCLS.

L8: (4) 17 and velcro

L10: (1) 19 and hook with loop

L11: (0) 19 and velcro

L12: (1092) 16 and velcro

L13: (1) 14 and velcro

L14: (1) 14 and hook with loop

L9: (167) (296/187.05).CCLS.

L15: (23) 13 and leather

L16: (1) ("3502056").PN.

L17: (1) ("5998015").PN.

L18: (1) ("4783114").PN.

Failed

(9260) 138/\$.ccls. and line\$

Saved

(5) ("5545361") or ("5799991") or ("5988713") or (

(7) ("5000510") or ("5101106") or ("5100007")

Search

List

Browse

Queue

Clear

DBs

USPAT

☒ Highlight all hit terms initially

4783114

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (42)

UDC

Queue

Trash

	U	1	Document ID	Issue Dat	Page	Title	Current
30	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 20020158486	20021031	8	Door for a vehicle, in particular a motor vehi	296/146
31	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6631940 B2	20031014	8	Door for a vehicle, in particular a motor vehi	296/146
32	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6207244 B1	20010327	10	Structural element and process for its product	428/35.
33	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6164716 A	20001226	10	Energy dissipating body panel assembly	296/187
34	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5395153 A	19950307	6	Motor vehicle side panel	296/146
35	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5306066 A	19940426	7	Energy absorbing vehicle doors	296/146
36	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5544913 A	19960813	7	Protective device for protecting vehicle occu	280/730
37	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4783114 A	19881108	5	Vehicle door and arm rest	296/153
38	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4456644 A	19840626	4	Cushioning body for the interior of a vehicle.	428/158
39	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3989275 A	19761102	3	Interior energy absorbing means for veh	280/751
40	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6485072 B1	20021126	20	Bumper system for motor vehicles	293/132
41	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5040335 A	19910820	5	Inner panel assembly with integral energy ab	49/502
42	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6177155 B1	20010123	15	Trim assembly for vehicle and method for	428/31

☒ Hits
 ☒ Details
 ☒ HTML

Ready

NUM

BEST AVAILABLE COPY

EAST - [lined duct:2]

File View Edit Tools Window Help

Pending

Active

- L1: (5) ("6,233,875") or ("6,447,047") or ("6,474,
- L2: (11) ("3,989,275") or ("4,848,829") or ("5,298
- L3: (214) (296/146.7).CCLS.
- L4: (326) (296/146.6).CCLS.
- L6: (188381) 15 and foam or styrene or urethane
- L7: (157) 15 and (foam or styrene or urethane)
- L5: (384) (280/751).CCLS.
- L8: (4) 17 and velcro
- L10: (1) 19 and hook with loop
- L11: (0) 19 and velcro
- L12: (1092) 16 and velcro
- L13: (1) 14 and velcro
- L14: (1) 14 and hook with loop
- L9: (167) (296/187.05).CCLS.
- L15: (23) 13 and leather
- L16: (1) ("3502056").PN.
- L17: (1) ("5998015").PN.
- L18: (1) ("4783114").PN.

Failed

- (9260) 138/\$.ccls. and line\$

Saved

- (5) ("5545361") or ("5799991") or ("5988713") or (

4783114

Search List Browse Queue Clear

DBs USPAT

☒ Highlight all hit terms initially

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (42)

UDC

Queue

Trash

	U	1	Document ID	Issue Dat	Page	Title	Current
17	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3623690	19711130	6	RELEASABLE HOLDDOWN	410/116
			A			DEVICE.	
18	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5298694	19940329	17	Acoustical insulating	181/286
			A			web	
19	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US	20030626	10	Vehicle part and method	296/146
			20030116993			of making same	
20	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US	20030102	14	Sealing systems and	296/146
			20030001408			related methods for aut	
21	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6619724	20030916	9	Motor vehicle door	296/146
			B2			comprising an insulatin	
22	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6447047	20020910	9	Vehicle door comprising	296/146
			B1			a panel attached direct	
23	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6422640	20020723	8	Door trim panel	296/146
			B1			assembly and method of	
24	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6412852	20020702	9	Water, dust and sound	296/146
			B1			attenuating barrier and	
25	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5456513	19951010	10	Sound and water barrier	296/39.
			A			and method of making th	
26	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5345721	19940913	6	Hook and pin fastener	49/502
			A			assembly for a door tri	
27	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5102163	19920407	18	Impact energy absorbing	280/751
			A			structure for a vehicle	
28	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4923542	19900508	6	Method of making a	156/92
			A			composite car door pane	
29	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US	20030508	5	Deformation element, in	296/146
			20030085588			particular for use in m	

Ready

NUM

BEST AVAILABLE COPY

EAST - [lined duct:2]

File View Edit Tools Window Help

Pending

Active

L1: (5) ("6,233,875") or ("6,447,047") or ("6,474,

L2: (11) ("3,989,275") or ("4,848,829") or ("5,298

L3: (214) (296/146.7).CCLS.

L4: (326) (296/146.6).CCLS.

L6: (188381) 15 and foam or styrene or urethane

L7: (157) 15 and (foam or styrene or urethane)

L5: (384) (280/751).CCLS.

L8: (4) 17 and velcro

L10: (1) 19 and hook with loop

L11: (0) 19 and velcro

L12: (1092) 16 and velcro

L13: (1) 14 and velcro

L14: (1) 14 and hook with loop

L9: (167) (296/187.05).CCLS.

L15: (23) 13 and leather

L16: (1) ("3502056").PN.

L17: (1) ("5998015").PN.

L18: (1) ("4783114").PN.

Failed

(9260) 138/\$.ccls. and line\$

Saved

(5) ("5545361") or ("5799991") or ("5988713") or (

(5) ("5545361") or ("5799991") or ("5988713") or (

Search

List

Browse

Queue

Clear

DBs

USPAT

☒ Highlight all hit terms initially

4783114

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (42)

UDC

Queue

Trash

	U	1	Document ID	Issue Dat	Page	Title	Current
4	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5484240	19960116	14	Releasable, modular, multi-use fastener for	410/110
5	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5316357	19940531	11	Extension wall attachment structure fo	296/36
6	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5141277	19920825	7	Stake pocket insert	296/43
7	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4815787	19890328	7	Mounting of a topper on a pickup truck	296/167
8	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4657299	19870414	11	Pickup truck tent pole anchor, operational com	296/159
9	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3595452	19710727	3	LOAD-CARRYING RACK FOR TRUCK BODIES AND THE LI	224/320
10	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2690351	19540928	5	Knockdown type cover for vehicle bodies	296/102
11	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5988472	19991123	9	Accessory mounting device for a vehicle	224/403
12	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5845952	19981208	12	Storage unit for pickup truck	296/37.
13	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5316366	19940531	6	Camper shell mounting rail	296/167
14	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5257848	19931102	7	Truck accessory support	296/156
15	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4627655	19861209	9	Pick-up cap construction	296/167
16	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3857601	19741231	4	CANOPY FOR PICKUP TRUCKS	296/10
17	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2623600	19711120	6	RELEASEABLE HOLDDOWN	410/110

Ready

NUM

BEST AVAILABLE COPY

EAST - [lined duct:2]

File View Edit Tools Window Help

Pending

Active

- L1: (5) (("6,233,875") or ("6,447,047") or ("6,474,
- L2: (11) ("3,989,275") or ("4,848,829") or ("5,298
- L3: (214) (296/146.7).CCLS.
- L4: (326) (296/146.6).CCLS.
- L6: (188381) 15 and foam or styrene or urethane
- L7: (157) 15 and (foam or styrene or urethane)
- L5: (384) (280/751).CCLS.
- L8: (4) 17 and velcro
- L10: (1) 19 and hook with loop
- L11: (0) 19 and velcro
- L12: (1092) 16 and velcro
- L13: (1) 14 and velcro
- L14: (1) 14 and hook with loop
- L9: (167) (296/187.05).CCLS.
- L15: (23) 13 and leather
- L16: (1) ("3502056").PN.
- L17: (1) ("5998015").PN.
- L18: (1) ("4783114").PN.

Failed

- (9260) 138/\$.ccls. and line\$

Saved

- (5) ("5545361") or ("5799991") or ("5988713") or (

Search

DBs USPAT

4783114

Highlight all hit terms initially

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (42)

UDC

Queue

Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error
1	IS&R	L1	5	(("6,233,875") or ("6,447,047") or ("6,	USPA	2004/10/2		
					T	8 07:17		
2	IS&R	L2	11	(("3,989,275") or ("4,848,829") or ("5,	USPA	2004/10/2		
					T	8 07:19		
3	IS&R	L3	214	(296/146.7).CCLS.	USPA	2004/10/2		
					T; U	8 08:53		
4	IS&R	L4	326	(296/146.6).CCLS.	USPA	2004/10/2		
					T; U	8 08:25		
5	BRS	L6	18838	15 and foam or	USPA	2004/10/2		
			1	styrene or urethane	T	8 08:27		
6	BRS	L7	157	15 and (foam or	USPA	2004/10/2		
				styrene or urethane)	T	8 08:28		
7	IS&R	L5	384	(280/751).CCLS.	USPA	2004/10/2		
					T; U	8 08:43		
8	BRS	L8	4	17 and velcro	USPA	2004/10/2		
					T	8 08:28		
9	BRS	L10	1	19 and hook with loop	USPA	2004/10/2		
					T	8 08:44		
10	BRS	L11	0	19 and velcro	USPA	2004/10/2		
					T	8 08:44		
11	BRS	L12	1092	16 and velcro	USPA	2004/10/2		
					T	8 08:44		
12	BRS	L13	1	14 and velcro	USPA	2004/10/2		
					T	8 08:46		

Ready

NUM

BEST AVAILABLE COPY